	OPERATIONS DEPARTMENT	R&F-OPDE-OP-FO-04
	INTEGRATED MANAGEMENT SYSTEM	REVISION N°: 1
	SERVICES DETECTION REPORT	ISSUE: APR/2021
		PAGE 1 OF 3

February 21, 2024

Economic Proposal #: R&F- 2724017	S. Order #: R&F-SO- 2724010	Service Report #: R&F-SDR- 2724007
-----------------------------------	-----------------------------	------------------------------------

CUSTOMER INFORMATION

CUSTOMER	SERVICE ADDRESS	# TELEPHONE	EMAIL
ITAC	3971 Elm Ave, Portsmouth, VA 23704	(804) 641-7336	jcollins@itac.us.com
SOLICITED SERVICE	SERVICE TO LOCATE:Gas Line PURPOSE:Excavation AREA: 60 x 10 Ft		

REPORT

TYPE OF SERVICE DETECTED	<input type="checkbox"/> Power	<input type="checkbox"/> Potable Water	<input checked="" type="checkbox"/> Gas	<input type="checkbox"/> Communications
	<input type="checkbox"/> Sewer	<input type="checkbox"/> Irrigation	<input type="checkbox"/> Rain water	<input type="checkbox"/> Proposed Excavation
DETECTED LENGTH	GPS COORDINATES	DEPTH OF SERVICE	MARKED COLORS	MARKED AREA
240'	N: 36.808, E: -76.295	4'. 0"	Yellow	Plan

COMMENTS

The following buried services were located

Gas Line. Depth 4' 0"

RECOMMENDATIONS:

Manual Excavation - 2 Feet from Marked Services

DATA OF THE EQUIPMENT USED FOR THE SERVICE

MODEL DETECTOR	SERIAL NUMBER	MODEL	DATE CALIBRATION	END CALIBRATION
RD-8100	10/81PDL-US-2542	RD8K1RX	10/23/2022	10/24/2024

DATA OF THE TECHNICIAN OPERATOR OF THE DETECTION EQUIPMENT

NAME OF THE TECHNICIAN	CERTIFICATION DATE	DAY OF SERVICE	Hours: From: - To:	QUA. HOURS	Job #
Eddison Rojas	26-Jun-12	2/21/2024	10:00 AM 12:00 PM	2:00	






CONSIDERATIONS TO TAKE INTO ACCOUNT:


a) The detected areas are those indicated by the Client, in the Stakeout, to make a Route Change. New Service Required

b) The Builder must compulsorily carry out exploratory pits, if it is going to cross an existing Service

c) The tolerance of the Service's location is 2 feet to both sides, from the brand.







d) The cables or pipe out of service, are not detected.


Produced by: <u>Eddison Rojas</u>	Approved by: <u>Edilberto Rojas</u>	SERVICE IDENTIFICATION CODE
Position: <u>Technical Locator</u>	Position: <u>Operations Coordinator</u>	 Communications
Date: <u>February 21, 2024</u>	Date: <u>February 21, 2024</u>	 Sewer
		 Rainwater
		 Gas
		 Potable Water

	OPERATIONS DEPARTMENT	R&F-OPDE-OP-FO-04
	INTEGRATED MANAGEMENT SYSTEM	REVISION N°: 1
	UNDERGROUND SERVICES DETECTION REPORT	ISSUE: APRIL/2021
		PAGE 2 DE 3


Photographic Record

<p align="center">Photo #: 001</p> 	<p align="center">Photo #: 002</p> 
<p align="center">Photo #: 003</p>	<p align="center">Photo #: 004</p>

Produced by: <u>Edison Rojas</u> Position: <u>Technical Locator</u> Date: <u>February 21, 2024</u>	Approved by: <u>Edilberto Rojas</u> Position: <u>Operations Coordinator</u> Date: <u>February 21, 2024</u>	SERVICE IDENTIFICATION CODE	
			Communications
			Sewer
			Rainwater
			Gas
			Potable Water
			Electric Power Lines

	OPERATIONS DEPARTMENT	R&F-OPDE-OP-FO-04
	INTEGRATED MANAGEMENT SYSTEM	REVISION N°: 1
	UNDERGROUND SERVICES DETECTION REPORT	ISSUE: APRIL/2021
		PAGE 3 of 3

SKETCH



Produced by: <u>Eddison Roias</u> Position: <u>Technical Locator</u> Date: <u>February 21, 2024</u>	Approved by: <u>Edilberto Roias</u> Position: <u>Operations Coordinator</u> Date: <u>February 21, 2024</u>	SERVICE IDENTIFICATION CODE	
			Communications
			Rainwater
			Sewer
			Gas
	Potable Water		
	Electric Power Lines		